



# ThruHoles in 3 Steps


Put a wire




Solder



Cut



Finished



Frgmnt / here


PRELIMINARY Berlin D

Jo frgmt Grys / frgmt.org / 2013

Transmitting Object Behaviors



# ThruHoles



# ThruHoles

